

## Dryer Vent Lint Filter Cleaning

All of the suites at the Bentley have a secondary dryer vent lint filter. These are designed to catch the bulk of the dryer lint which is not captured by the dryer's internal filter. It is very important that these be cleaned at least monthly but more frequently if the dryer has heavy use. Failure to do so will cause your dryer to operate less efficiently, take longer to dry your laundry and contribute to excessive moisture build-up in your suite.

The secondary dryer lint filter looks like this:



To clean the lint filter, lift up on the knob, pull it away from the metal filter housing, then pull it down to remove the plexiglass cover along with the attached filter screen:



Over a garbage receptacle, remove the accumulated lint from the screen:



**Note:** If there is as much lint buildup as in the example, the filter needs to be cleaned much more often!

Brush or vacuum the screen to remove any remaining lint:



Replace the filter by engaging the top of the plexiglass cover under the flange at the top of the filter housing and then push the knob up, and then in and down to engage the bottom of the cover in the flange at the bottom of the housing:

